## AVIVA CANADA INC. CLAIMS CARE CENTER 211 Pritchard Road - Suite No. Unit 4 Hamilton Ontario L8J 0G5 1-866-692-8482

#### \*\*\* PRELIMINARY ESTIMATE \*\*\*

27/03/2017 11:31 AM

Owner

Owner: Eva Gervais

Address: 9963 Wilde Road SE

City Province Postal: Calgary, AB T2J 1G6

Email: gervaise.eg@gmail.com

Home/Day: (403)808-6161

FAX:

Insured Policy #: A15278429PLA

Loss Type: Collision

Work/Day: (866)692-8482

Work/Day: (306)352-1664

Home/Day: (403)808-6161

Work/Day: (306)352-1664

FAX: (866)805-8585

**Control Information** 

Claim #: 33890500

Loss Date/Time: 09/03/2017 06:00 AM

**Deductible: \$1,000.00** 

Ins. Company: Personal Lines (Aviva)

Address: 1 KING ST WEST

City Province Postal: Hamilton, ON L8P 1A4

Agent: ANGELA BANK (Claimspro.SCM)

Address: 436 MCDONALD STREET

City Province Postal: REGINA, SK S4N 6E1

Email: angela.bank@scm.ca

Insured: Eva Gervais

Address:

City Province Postal: T2J 1G6

Email: gervaise.eg@gmail.com

Claim Rep: ANGELA BANK (Claimspro.SCM)

Address: \*March 24\* 9963 Wilde Road SE

Address: 436 MCDONALD STREET

City Province Postal: REGINA, SK S4N 6E1

Email: angela.bank@scm.ca

Contact:

Home/Day: (403)808-6161x

City Province Postal: Calgary, AB T2J 1G6

Inspection Date: 27/03/2017 11:29 AM

Inspection Location: INSURED WORK PLACE

Primary Impact: Rear

Driveable: Yes

First Contact Date/Time:

Assigned Date/Time:

Appraiser Name: LYLE FISHER

Address:

City Province Postal: CALGARY, AB

Email: lyle\_fisher@avivacanada.com

Inspection Type: Field

Secondary Impact:

Rental Assisted: Yes

Received Date/Time: 24/03/2017 09:56 AM Appointment Date/Time: 27/03/2017 06:00 AM

Appraiser License #:

Cell: (403)813-8963

Work/Day: (403)254-7400

FAX: (403)254-7401

Inspection

Repairer

Repairer: A1 AUTOBODY

Address: 5304 1a STREET SE City Province Postal: Calgary, AB T2H 1J2

Email: mmcalister@a1autobody.com

Contact: MIKE BLANK Work/Day: (440)325-3786x7

#### Remarks

All supplements will require APROVAL BEFORE WORK IS STARTED PLEASE CALL

Any addition damage or parts must have supporting photos before primer

Please provide all invoices for final

Please take supporting photos after tear down

POSSIBLE HIDDEN DAMAGE TEAR DOWN REQUIRED FOR PROPER ESTIMATE

**BOOKED AT A1 AUTOBODY CALGARY** 

AVIVA WILL NOT PAY MORE THAN MSRP ON PARTS

\*\*\*\* SUPPLEMENTS NEED PHOTOS + COPIES OF ALL PARTS INVOICES FOR APPROVAL \*\*\*

\*\*\*\* AVIVA PAYS MATERIALS ON REPAIR AND WELD ON LABOR ONLY \*\*\*\*

PLEASE NOTE AVIVA USES APU PARTS SEARCH TOOL

#### Vehicle

2008 Toyota Yaris LE 4 DR Hatchback 4cyl Gasoline 1.5 4 Speed Automatic

Lic.Plate: EKS851

Lic Expire: Prod Date: Veh Insp# :

Condition: Fair

Ext. Colour: GOLD ORANGE Ext. Refinish: Two-Stage Ext. Paint Code: 4S9 Lic Province: AB

VIN: JTDKT923X85143340

Kilometer: 304,267 Kilometer Type: Actual Code: Y1443A

Int. Colour: Int. Refinish: Int. Trim Code:

### **Options**

AM/FM CD Player
Bucket Seats
Engine Block Heater
Keyless Entry System
Power Brakes
Power Steering

Power Steering Rear Window Wiper/Washer Tinted Glass Air Conditioning Center Console Fog Lights

Leather Steering Wheel Power Door Locks Power Windows

Tachometer Upgraded/Add'l Speakers Anti-Lock Brakes Dual Airbags Intermittent Wipers Mud/Splash Guards

Power Mirrors

Rear Window Defroster Tilt Steering Wheel Velour/Cloth Seats

## Damages

Line Op	Guide	MC Description	MFR.Part No.	Price	ADJ% B%	Hours	R
1 RI	458	Guard,Mud LT	R & I Assembly			INC	SM
2 RI	459	Guard,Mud RT	R & I Assembly			INC	SM
3 N	562	RR Bumper Cvr Overhaul	Additional Labour			1.9	SM
4 1	566	Cover,Rear Bumper	Repair			4.0*	SM
5 L	566	13 Cover,Rear Bumper	Refinish 2.5 Surface			3.6	RF
			0.6 Two-stage setup				

2008 10yota Yans LE 4 DR Hatchbac Claim #: 33890500	A.C.						2/103/	2017 11:31
			0.5 T	wo-stage				
6 SB	Hazardous W	aste Removal	Sublet Re		\$5.00			SM
7 L	Flex Additive	Flex Additive Refinish \$15			\$15.00			RF
8 SB	Reset Electrical Component Sublet Repair \$1.00*  >> PRE/POST SCAN PRINT REQ TO CONFIRM AIR BAG LITE FROM THIS LOS						SM	
	>> PRE/POS	T SCAN PRINT	REQ TO C	ONFIRM AIR	BAG LITE FR	OM THIS LOSS		
8 Items								
	MC	Message						
	13	INCLUDES 0.6	HOURS F	IRST PANEL	TWO-STAGE	ALLOWANCE		
Estimate Total & Entri	ies							
Other Parts						\$15.00		
Paint & Materials	3.6 Hours @ \$32.00				\$115.20			
Shop Materials	5.9 Hours @ \$10.00				\$59.00			
Parts & Material Total			_				\$189.20	
	<b>D</b> . (-	Daniera D	an ain Usa	Total Hrs				
_abour	Rate	Replace R Hrs	epair nis	10tal His				
Sheet Metal (SM)	\$70.00	-	5.9	5.9	\$413.00			
Nech/Elec (ME)	\$80.00							
Frame (FR)	\$75.00							
Refinish (RF)	\$70.00	3.6		3.6	\$252.00			
_abour Total				9.5 H		\$665.00		
Sublet Repairs		_	= 0000/		\$6.0	u \$43.01		
Boods & Services Tax		@ 5.000%				\$903.21		
Gross Total					\$1,000.00	_		
Less: Deductible	( ¢ 06 70 )				\$0.00			
Net Total		( \$-96.79 )				Ψ0.00		

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00 Postal Code: T3L 2V8 Default Rate Name CALGARY DRP

Audatex Estimating 8.0.134 ES 27/03/2017 11:42 AM REL 8.0.134 DT 01/03/2017 DB 15/03/2017 © 2017 Audatex North America, Inc.

# 1.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS IS NOT AN AUTHORIZATION FOR REPAIRS. THIS ESTIMATE WILL ONLY BE VALID FOR A 30-DAY PERIOD AND CANNOT BE CONSIDERED FINAL. THE ESTIMATE MAY INCLUDE REBUILT, RECYCLED AND QUALITY REPLACEMENT PARTS COVERED BY THE MANUFACTURER'S GUARANTEE. THE INSURER HAS THE RIGHT TO NEGOTIATE WITH THE REPAIRER AND DEMAND AT ALL TIMES INVOICES FOR PARTS. REGISTRANT IS RESPONSIBLE FOR APPLICABLE TAXES UPON PRESENTATION OF INVOICES. REPAIRS ARE TO BE AUTHORIZED SOLELY BY THE POLICYHOLDER/CLAIMANT.

#### Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS

EC = Replace Economy

ET = Partial Replace Labour

TE = Partial Replace Price

L = Refinish

TT = Two-Tone BR = Blend Refinish

CG= Chipguard

AA = Appearance Allowance

OE = Replace PXN OE Srpls

EP = Replace PXN

PM= Replace PXN Reman/Reblt PC = Replace PXN Reconditioned

SB = Sublet Repair

I = Repair

RI = R & I Assembly

RP = Related Prior Damage

UE = Replace OE Surplus

EU = QLTY RECYCLED PART

UM= Replace Reman/Rebuilt

UC = Replace Reconditioned

N = Additional LabourIT = Partial Repair

P = Check



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2017 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

